


This is the tab that will help release snap-fit assembly.

Using a flathead screwdriver, slide/wedge head between base and grill, aligned with the corner tab. Apply a building pressure until a distinct "POP" is heard.



The "POP" noise indicates the snapfit has partially unseated from the base. Gently rock screwdriver around until grill can be removed.

